

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-021239**Date Inspected:** 19-Feb-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Geng Wei**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Components**Summary of Items Observed:**

On this date Caltrans Office of Structural Materials Quality Assurance Inspector, Sandeep Kumar (QA) was present during the times noted above for observations relative to the work being performed.

BAY#14

East Side

This QA Inspector observed the following work in progress

Shielded Metal Arc Welding (SMAW):

Weld joint #070 located on 13AE, SEG3007L. Welder is identified as 066163. ZPMC Quality Control (QC)

Inspector is identified as Wang Xu. The welding variables recorded by QC appeared to comply with the

WPS-B-P-2213-B-U2-FCM-1.

Repair welding of a weld joint #036 located on 13AE, SEG3007AB as per the weld repair report# WR-19314.

Welder is identified as 037723. ZPMC Quality Control (QC) Inspector is identified as Wang Xu. The welding

variables recorded by QC appeared to comply with the WPS-345-SMAW-4G (4F)-REPAIR-1. (See attached photo)

Weld joint #031 located on 13AE, SEG3007AU. Welder is identified as 70007. ZPMC Quality Control (QC)

Inspector is identified as Wang Xu. The welding variables recorded by QC appeared to comply with the

WPS-B-P-2213-B-U2-FCM-1.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

Weld joint #074 located on 13AE, SEG3007L. Welder is identified as 066163. ZPMC Quality Control (QC) Inspector is identified as Wang Xu. The welding variables recorded by QC appeared to comply with the WPS-B-P-2213-B-U2-FCM-1.

Weld joint #035 located on 13AE, SEG3007AU. Welder is identified as 70007. ZPMC Quality Control (QC) Inspector is identified as Wang Xu. The welding variables recorded by QC appeared to comply with the WPS-B-P-2213-B-U2-FCM-1.


Flux Cored Arc Welding (FCAW):

Weld joint #001 located on 13AE, SEG3007G. Welder is identified as 055564. ZPMC Quality Control (QC) Inspector is identified as Wang Xu. The welding variables recorded by QC appeared to comply with the WPS-B-T-2232-ESAB.

Weld joint #220 located on 13AE, SEG3007D. Welder is identified as 055491. ZPMC Quality Control (QC) Inspector is identified as Wang Xu. The welding variables recorded by QC appeared to comply with the WPS-B-T-2232-ESAB.

Weld joint #001 located on 13AE, SEG3007G. Welder is identified as 055491. ZPMC Quality Control (QC) Inspector is identified as Wang Xu. The welding variables recorded by QC appeared to comply with the WPS-B-T-2232-ESAB.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



Summary of Conversations:

No Relevant Conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang - 15000422372, who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Inspected By:	Kumar,Sandeep	Quality Assurance Inspector
Reviewed By:	Patterson,Rodney	QA Reviewer
